



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-04-12
Tel.	: 0873663242	Lemon Inspection ID	: LEMON24040087
Inspector	: Natthapong Tong Suksing	Approved By	:

Details

Brand	MERCEDES BENZ	Model year	2021
Model	A200	Engine Code - No.	28291430687714
Sub-model	Progressive	Registration year	2022-03-03
Registration No.	2๒๘9907	Chassis No.	W1K1771876L003762
Current Mileage(km.)	40171	Engine Capacity(cc.)	1300

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★


This vehicle has been inspected by the SCHICHER's inspection service.

Inspector


Natthapong Tong Suksing

Approved By

Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image




Vehicle Front Right Image



Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




OBD Vehicle Identity Analysis




Vehicle Registration Book




Vehicle Engine Number Image



OBD Vehicle Health Analysis



Passenger Back Seat Image



Passenger Front Console Image




Passenger Ceiling Part Image



Passenger Front Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		

Main Status




BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	1522	4
2. Front Right Tire Condition	Normal	1522	4
3. Back Left Tire Condition	Normal	1522	4
4. Back Right Tire Condition	Normal	1522	4



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.48
3. Charging Voltage(V.)	13.3

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

















Chassis Damage Level	No Damage
----------------------	-----------








Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Console	
2. Dashboard	
3. Steering wheel and control panel	
4. Sound system and monitor	
5. Air conditioning system	
6. Front left door panel	
7. Left power window master	
8. Front left seat	
9. Front right seat	
10. Window control switch, front right door	
11. Front right door panel	
12. Right rear door panel	
13. Right rear power window master switch	
14. Rear Seat 1	
15. Rear Seat 2	
16. Rear Seat 3	

17. Left rear power window master switch	
18. Left rear door panel	
19. Luggage storage area	
20. Gear knob	
21. Left Headliner	
22. Right Headliner	
23. Rear	

Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report

Evidence of Flood	No
-------------------	----



Fire Report

Evidence of Fire	No
------------------	----



Inspector Note

Vehicle : MERCEDES BENZ A200 2ขย9907

Chassis number : W1K1771876L003762

Inspection date : 2024-04-12

Inspector : ***รุ่นย่อยรถยนต์ Mercedes-Benz A200 Progressive *** ภายนอก ตรวจสอบไม่พบหลักฐานการ
ทำสี สภาพดีสวยครับ มีรอยขีดข่วนบนแฉวเล็กน้อยจางๆสามารถขัดสีออกได้ ยางรถยนต์ทั้ง 4 เส้นปกติปี 2022
ภายใน สะอาดเรียบร้อยปกติ แอร์เครื่องเสียงวิทยุ multi function ใช้งานได้ปกติ เครื่องยนต์ ตรวจสอบทำงานปกติ ไม่
พบรอยรั่วซึม ตรวจสอบด้วยเครื่องสแกน obd2 ไม่พบรหัสปัญหาที่ผิดปกติ ไม่ได้ทดสอบขับเคลื่อน โครงสร้าง ตรวจสอบ
ปกติ

Vehicle Certification : Pass the inspection standard of Schic inspection by Lemon-aide