



# Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-06-21
Tel.	: _____	Lemon Inspection ID	: LEMON24060221
Inspector	: ແກ່າວສັກ ຖອຍ ທີພຍອິນທີ	Approved By	: Chaimongkol C

**Details**

Brand	MERCEDES BENZ	Model year	2019
Model	GLC250	Engine Code - No.	27492031674104
Sub-model	d 4MATIC (AMG Dynamic)	Registration year	2019-08-07
Registration No.		Chassis No.	WDC2533466L019809
Current Mileage(km.)	44702	Engine Capacity(cc.)	2000

**Inspection Lists****Grading**

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

ແກ່າວສັກ ຖອຍ ທີພຍອິນທີ

Approved By

Chaimongkol C

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image



Vehicle Rear Right Image



## Vehicle Registration Book



## Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis



Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



## Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

**Exterior Inspection Report**

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S2)	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front windshield	O (G1)
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left door	O (S1)	25. Back Windshield	O
13. Front Left Door	O		

**Main Status**

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

**Sub Status**

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices







Vehicle Defect Notices



## Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Worn Down	1022	4
2. Front Right Tire Condition	Bald Tire	1022	4
3. Back Left Tire Condition	Normal	1222	4
4. Back Right Tire Condition	Normal	1322	5



## Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12
3. Charging Voltage(V.)	14

## Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

## Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

## Interior Report

1. Console	<div style="width: 100%; background-color: #00AEEF;"></div>
2. Dashboard	<div style="width: 100%; background-color: #00AEEF;"></div>
3. Steering wheel and control panel	<div style="width: 100%; background-color: #00AEEF;"></div>
4. Sound system and monitor	<div style="width: 100%; background-color: #00AEEF;"></div>
5. Air conditioning system	<div style="width: 100%; background-color: #00AEEF;"></div>
6. Front left door panel	<div style="width: 100%; background-color: #00AEEF;"></div>
7. Left power window master	<div style="width: 100%; background-color: #00AEEF;"></div>
8. Front left seat	<div style="width: 100%; background-color: #00AEEF;"></div>
9. Front right seat	<div style="width: 100%; background-color: #00AEEF;"></div>
10. Window control switch, front right door	<div style="width: 100%; background-color: #00AEEF;"></div>
11. Front right door panel	<div style="width: 100%; background-color: #00AEEF;"></div>
12. Right rear door panel	<div style="width: 100%; background-color: #00AEEF;"></div>
13. Right rear power window master switch	<div style="width: 100%; background-color: #00AEEF;"></div>
14. Rear Seat 1	<div style="width: 100%; background-color: #00AEEF;"></div>
15. Rear Seat 2	<div style="width: 100%; background-color: #00AEEF;"></div>
16. Rear Seat 3	<div style="width: 100%; background-color: #00AEEF;"></div>

17. Left rear power window master switch	
18. Left rear door panel	
19. Luggage storage area	
20. Gear knob	
21. Left Headliner	
22. Right Headliner	
23. Rear	

**Vehicle Overview**

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

**Flood Report**


Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



## Inspector Note

**Vehicle :** MERCEDES BENZ GLC250**Chassis number :** WDC2533466L019809**Inspection date :** 2024-06-21

**Inspector :** ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมไม่พบหลักฐานการซ่อมแซมทำสี รั้วรอยเล็กน้อย/สภาพยางกั้ง4เส้น ปี 22 เสื่อมสภาพหน้าซ้ายขวา กันชนหน้าบุดคลอก กระจกบังลมหน้ามีรอยสะเก็ดหิน ภายใน(Interior) : ภายในตรวจพบตัวสวิตซ์พับเบาะหลังชำรุด สาขาวิศรีบปรับอุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้ สมบูรณ์ครบถ้วน เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่สามารถตรวจส่องได้ รุนไม่รับรอง (ไม่ได้ทดสอบขับขี่) โครงสร้าง(Frame) : อุบัติเหตุไม่มี โครงสร้างหลักปกติ ไม่มีการซ่อมแซม โครงสร้างหรือมีการชนถึงโครงสร้าง

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE