

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-08
Tel.		Lemon Inspection ID	: LEMON24070119
Inspector	: แทนรัก ทิพย์อินทร์	Approved By	: ไซยมงคล ไพรเลี้ยง

### Details

Brand	MERCEDES BENZ	Model year	2019
Model	GLC220	Engine Code - No.	65192165023268
Sub-model	d AMG Dynamic	Registration year	2024-07-08
Registration No.		Chassis No.	WDC2539056L022987
Current Mileage(km.)	99858	Engine Capacity(cc.)	2200

### Inspection Lists


### Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector	แทนรัก ทิพย์อินทร์	Approved By	ไซยมงคล ไพรเลี้ยง
-----------	--------------------	-------------	-------------------

**Vehicle Front Image**



**Vehicle Back Image**



**Vehicle Front Left Image**



**Vehicle Front Right Image**





Vehicle Rear Left Image



Vehicle Rear Right Image





**Vehicle Registration Book**

รายการจดทะเบียน M 098501


วันจดทะเบียน 2 ธันวาคม 2562 เลขทะเบียน 1 จังหวัด กรุงเทพมหานคร  
 ประเภท รถยนต์ส่วนบุคคลไม่เกิน 7 คน (ราย 1) ลักษณะ เก่งสองคนแวน  
 ยี่ห้อรถ MERCEDES BENZ แบบ GLC 220 d 4MATIC รุ่นปี ค.ศ. 2019  
 สี เทา เลขตัวรถ WDC2539056L022987 อยู่ที่ โต๊ะนั่งขวา  
 ยี่ห้อเครื่องยนต์ MERCEDES BENZ เลขเครื่องยนต์ 65192135023268  
 อยู่ที่ ซ้ายเครื่อง เชื้อเพลิง ดีเซล เลขถังแก๊ส  
 จำนวน 4 สูบ 2143 ซีซี 170 แรงม้า 2 พลา 4 ล้อ ยาง 4 เส้น  
 น้ำหนักรถ 1800 กก. น้ำหนักบรรทุก/น้ำหนักลงเสา กก.  
 น้ำหนักรวม 1800 กก. ที่นั่ง 5 คน 10351141

เจ้าของรถ  
 ผู้ถือกรรมสิทธิ์ ลำดับที่ 1 วันที่ครอบครองรถ 2 ธันวาคม 2562  
 บริษัทเมอร์เซเดส-เบนซ์ ลิมิเต็ด (ประเทศไทย) จำกัด

**Vehicle Engine Image**



Vehicle Odometer Image




Vehicle Chassis Image







**Vehicle Engine Number Image**




**OBD Vehicle Identity Analysis**



**OBD Vehicle Health Analysis**




**Passenger Front Console Image**







**Passenger Front Seat Image**



**Passenger Ceiling Part Image**




**Passenger Back Seat Image**





## Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

### Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	BP	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front bonnet	O (G1)	20. Back right wheel	O (S1)
8. Right Wing Mirror	O	21. Rear Bumper	O (S1)
9. Front right door	O (S1)	22. Rear Skirt	O
10. Rear right door	O (D1)	23. Rear Left Fender	O
11. Right Skirt	O	24. Back left wheel	O (S2)
12. Rear Left door	BP (S1)	25. Back Windshield	O
13. Front left door	BP		

#### Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

#### Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade



**Vehicle Defect Notices**



**Vehicle Defect Notices**






**Vehicle Defect Notices**





**Vehicle Defect Notices**







**Vehicle Defect Notices**



### Tire Condition Report

Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2921	4
2. Front Right Tire Condition	Normal	0921	4
3. Back Left Tire Condition	Bald Tire	0921	3
4. Back Right Tire Condition	Bald Tire	0921	3




### Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12
3. Charging Voltage(V.)	14



**Chassis Report**



**Damage Level**

No Damage

Level A


Level B

Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS













Chassis Damage Level	No Damage
----------------------	-----------

### Interior Inspection Points










Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

### Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	



17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



### Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

**Flood Report**

Evidence of Flood


No



**Fire Report**

Evidence of Fire

No





**Inspector Note****Vehicle :** MERCEDES BENZ GLC220**Chassis number :** WDC2539056L022987**Inspection date :** 2024-07-08

**Inspector :** ภายนอก(Exterior) : การตรวจสอบสภาพภายนอกโดยรวมพบหลักฐานการซ่อมแซมทำสีมาบ้างชิ้นฟุ้งซ้าย/สภาพยางทั้ง4เส้น ปี 21 เสื่อมสภาพยางหลังคู่ ล้อแม็กเป็นรอยถลอก ภายใน(Interior) : ภายในเบาะหน้าซ้ายขวา ถลอก/สะอาดเรียบร้อย อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ วิเคราะห์ปัญหาด้วยเครื่อง OBDII พบสิ่งผิดปกติ แนะนำตรวจเช็คศูนย์บริการ (ไม่ได้ทดสอบขับขึ้น) โครงสร้าง(Frame) : อุบัติเหตุไม่มี โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE