



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-11
Tel.	:	Lemon Inspection ID	: LEMON24070171
Inspector	: แทนรัก ทิพย์อินทร์	Approved By	: ไชยมงคล ไพโรเสียง

Details

Brand	MERCEDES BENZ	Model year	2018
Model	CLA200	Engine Code - No.	27091031720753
Sub-model	URBAN	Registration year	2020-07-21
Registration No.		Chassis No.	WDD1173436L010878
Current Mileage(km.)	283770	Engine Capacity(cc.)	1600

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★


This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector	แทนรัก ทิพย์อินทร์	Approved By	ไชยมงคล ไพโรเสียง
-----------	--------------------	-------------	-------------------


Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image




Vehicle Front Right Image



Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Registration Book

M94934 4

รายการจดทะเบียน

วันจดทะเบียน 21 กรกฎาคม 2563 เลขทะเบียน 194934

ประเภท รถยนต์นั่งส่วนบุคคลไม่เกิน 7 คน (รย. 1) ลักษณะ เก๋งสองคน

ยี่ห้อรถ MERCEDES BENZ แบบ CLA200 รุ่นปี ค.ศ. 2018

สี เทา เลขตัวรถ WDD1173436L010878 อยู่ที่ ดุสิตธานี

ยี่ห้อเครื่องยนต์ MERCEDES BENZ เลขเครื่องยนต์ 27091031720753

อยู่ที่ ชาวโคราช เชื้อเพลิง เบนซิน เลขถังแก๊ส

จำนวน 4 สูบ 1595 ซีซี 156 แรงม้า 2 เฟลา 4 ล้อ ยาง 4 เส้น

น้ำหนักรถ 1450 กก. น้ำหนักบรรทุก/น้ำหนักลงเฟลา กก.

น้ำหนักรวม 1450 กก. ที่นั่ง 5 คน

62-0521046

เจ้าของรถ


ลำดับที่ 1 วันที่ครอบครองรถ 21 กรกฎาคม 2563

ผู้ออกรรณสิทธิ์ ขวัญใจเพชร 163-163-163 (ประจักษ์ 163-163-163)

Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis




OBD Vehicle Health Analysis




Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	BP (S1,Y)	15. Left Wing Mirror	O
3. Front Right Fender	O (S1)	16. Front windshield	N (G1)
4. Front Right Wheel	O (S1)	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front bonnet	BP (S1)	20. Back right wheel	O (S1)
8. Right Wing Mirror	O	21. Rear Bumper	BP
9. Front right door	O (S1)	22. Rear Skirt	O
10. Rear right door	O (S1)	23. Rear Left Fender	O
11. Right Skirt	O	24. Back left wheel	O (S1)
12. Rear Left door	BP (S1)	25. Back Windshield	O
13. Front left door	BP		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing



Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices





Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	4923	5
2. Front Right Tire Condition	Normal	4923	5
3. Back Left Tire Condition	Normal	2923	5
4. Back Right Tire Condition	Normal	2923	5



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12
3. Charging Voltage(V.)	13.9

Chassis Report



Damage Level

No Damage

Level A


Level B

Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS











Chassis Damage Level	No Damage
----------------------	-----------








Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	


Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report

Evidence of Flood



No



Fire Report

Evidence of Fire

No



Inspector Note**Vehicle :** MERCEDES BENZ CLA200**Chassis number :** WDD1173436L010878**Inspection date :** 2024-07-11

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอก โดยรวมพบหลักฐานการซ่อมแซมทำสีมาบ้างชิ้น ไร้รอยถลอกรอบคัน / สภาพยางปกติทั้ง4เส้น ปี 23 ล้อแม็กเป็นรอยถลอก ภายใน(Interior) : ภายในเบาะหน้าขวาเป็นรอยขาด ตัวเปิดเบาะหน้าซ้ายชำรุด สะอาดเรียบร้อย , อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้ตามมาตรฐานครบปกติ

เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิดปกติ (ไม่ได้ทดสอบขับขี) เครื่องมีรอยรั่วน้ำมันเล็กน้อย

โครงสร้าง(Frame) : อุบัติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE