



Preowned Vehicle Inspection Report

Premium Inspection Analysis

| | | | |
|---------------|-----------------------------------------------|---------------------|----------------------|
| Customer Name | : MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD. | Inspection Date | : 2024-07-17 |
| Tel. | : | Lemon Inspection ID | : LEMON24070284 |
| Inspector | : ไซบงคล ไพรเลี้ยง | Approved By | : แทนรัก ทิพย์อินทร์ |

Details

| | | | |
|----------------------|-----------------------|----------------------|-------------------|
| Brand | MERCEDES BENZ | Model year | 2019 |
| Model | GLC250 | Engine Code - No. | 27492031771509 |
| Sub-model | COUPE 4MATIC AMG PLUS | Registration year | 2019-08-30 |
| Registration No. | | Chassis No. | WDC2533466L023605 |
| Current Mileage(km.) | 80025 | Engine Capacity(cc.) | 2000 |

Inspection Lists

Grading

| | |
|------------------------|-------|
| 1. Exterior | ★★★★★ |
| 2. Chassis | ★★★★★ |
| 3. Interior | ★★★★★ |
| 4. Engine & Mechanical | ★★★★★ |
| 5. Overall | ★★★★★ |

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

ไซบงคล ไพรเลี้ยง


Approved By

แทนรัก ทิพย์อินทร์

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image




Vehicle Rear Right Image



Vehicle Registration Book



Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis



Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



| Exterior Status | |
|-----------------|--------------------|
| O | Original |
| N | New Parts |
| BP | New Body Paint Job |
| X | Need Replacing |

Exterior Inspection Report

| | | | |
|-----------------------|--------|-----------------------|---|
| 1. Front Skirt | O | 14. Left Skirt | O |
| 2. Front Bumper | O (S2) | 15. Left Wing Mirror | O |
| 3. Front Right Fender | O | 16. Front Windshield | O |
| 4. Front Right Wheel | O | 17. Roof | O |
| 5. Front Left Fender | O | 18. Rear Right Fender | O |
| 6. Front Left Wheel | O | 19. Rear Bonnet | O |
| 7. Front Bonnet | O | 20. Back Right Wheel | O |
| 8. Right Wing Mirror | O | 21. Rear Bumper | O |
| 9. Front Right Door | O | 22. Rear Skirt | O |
| 10. Rear Right Door | O | 23. Rear Left Fender | O |
| 11. Right Skirt | O | 24. Back Left Wheel | O |
| 12. Rear Left Door | O | 25. Back Windshield | O |
| 13. Front Left Door | O | | |

Main Status

| | |
|----|--------------------|
| BP | New Body Paint Job |
| N | New Parts |
| O | Original |
| X | Need Replacing |

Sub Status





| | | | |
|---|-----------|---|---------------------|
| S | Scratched | G | Stone Chip on Glass |
| D | Dent | Y | Cracked |
| R | Rust | E | Dimple |
| C | Corrosion | F | Paint Fade |

Vehicle Defect Notices



Tire Condition Report


| Conditions Report | Tire Status | Date Code | Tire Depth(mm) |
|-------------------------------|-------------|-----------|----------------|
| 1. Front Left Tire Condition | Normal | 4322 | 4 |
| 2. Front Right Tire Condition | Normal | 4322 | 4 |
| 3. Back Left Tire Condition | Normal | 2221 | 4 |
| 4. Back Right Tire Condition | Normal | 2221 | 5 |



Battery Condition Report

| Conditions Report | Details |
|-------------------------|---------|
| 1. Battery Status | Pass |
| 2. Resting Voltage(V.) | 12 |
| 3. Charging Voltage(V.) | 15 |

Chassis Report




| Damage Level |
|--------------|
| No Damage |
| Level A |
| Level B |
| Level C |

| | |
|-----------------------------------------------------------|------|
| No dent in the under carriage (th) | PASS |
| No deform chassis or chassis frame (th) | PASS |
| No visible corrosion on the chassis or chassis frame (th) | PASS |
| No missing part on the chassis frame (th) | PASS |
| Half cut Analysis (th) | PASS |

| | |
|----------------------|-----------|
| Chassis Damage Level | No Damage |
|----------------------|-----------|

Interior Inspection Points



| | |
|-----------------------------|---|
| Scratched/Faded items | S |
| Sunken/Sagging car seats | D |
| Tear/Cracks | Y |
| Failed Electrical Equipment | E |

Interior Report

| | |
|---------------------------------------------|---------------------------------------------------------------------------|
| 1. Dashboard | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 2. Sound system and monitor | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 3. Air conditioning system | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 4. Console | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 5. Steering wheel and control panel | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 6. Gear knob | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 7. Left Headliner | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 8. Right Headliner | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 9. Left power window master | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 10. Front left door panel | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 11. Front left seat | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 12. Front right seat | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 13. Window control switch, front right door | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 14. Front right door panel | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 15. Right rear power window master switch | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |
| 16. Right rear door panel | <div style="width: 100%; background-color: #2e8b57; height: 10px;"></div> |

| | |
|------------------------------------------|-------------------------------------------------------------------------------------|
| 17. Left rear power window master switch |  |
| 18. Rear Seat 1 |  |
| 19. Rear Seat 2 |  |
| 20. Rear Seat 3 |  |
| 21. Left rear door panel |  |
| 22. Luggage storage area |  |
| 23. Rear |  |

Vehicle Overview

| | | | |
|------------------------------------------------------|------|----------------------------------------------|------|
| 1. Vehicle Engine Number Analysis (th) | PASS | 14. Air Conditioning and Heating System (th) | PASS |
| 2. Vehicle Chassis Number Analysis (th) | PASS | 15. Front and Rear Suspension (th) | PASS |
| 3. Vehicle Original OEM Color Analysis (th) | PASS | 16. Drive Axle (th) | PASS |
| 4. Engine System (th) | PASS | 17. High Tech (th) | PASS |
| 5. Transmission System (th) | PASS | 18. Passenger Comfort (th) | PASS |
| 6. Electrical System (th) | PASS | 19. Security System (th) | PASS |
| 7. Brake System (th) | PASS | 20. Safety Active (th) | PASS |
| 8. Steering System (th) | PASS | 21. Safety Passive (th) | PASS |
| 9. Fuel System (th) | PASS | 22. Original Mileage Analysis (th) | PASS |
| 10. Four-wheel Drive (th) | PASS | 23. Overall Chassis Analysis (th) | PASS |
| 11. Turbocharger/Supercharger (th) | PASS | 24. Overall Exterior Analysis (th) | PASS |
| 12. Fuel Injection and Engine Management System (th) | PASS | 25. Overall Interior Analysis (th) | PASS |
| 13. Engine Cooling System (th) | PASS | | |

Flood Report

Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ GLC250**Chassis number :** WDC2533466L023605**Inspection date :** 2024-07-17

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมไม่พบหลักฐานการซ่อมทำสี/พับกันชนหน้ารถลอก/คั่วล้อหลังข้ามล้อ / สภาพยางปักติดกัน 4 เส้น ปี 22 หลังขวางปี 21 ภายใน(Interior) : ภายในปักติด สะอาดเรียบร้อย , อุปกรณ์ไฟฟ้า แอร์ วิทยุ FM ใช้งานได้ลื่นบูรณาครุปปักติ เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปักติ , วิเคราะห์ปัญหาด้วยเครื่อง OBDII พับสั่งผิดปักติ แนะนำเข้าศูนย์บริการใหม่ได้ทดสอบขับขี่ โครงสร้าง(Frame) : อุบัติเหตุไม่มี , โครงสร้างหลักปักติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE