



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-18
Tel.	:	Lemon Inspection ID	: LEMON24070318
Inspector	: ไซบงคล ไพรเลี้ยง	Approved By	: แทนรัก ทิพย์อินทร์

Details

Brand	MERCEDES BENZ	Model year	2019
Model	GLC250	Engine Code - No.	27492031706141
Sub-model	4MATIC AMG PLUS (COUPE)	Registration year	2020-03-24
Registration No.	9กง6594	Chassis No.	WDC2533466L021060
Current Mileage(km.)	30880	Engine Capacity(cc.)	2000

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

ไซบงคล ไพรเลี้ยง


Approved By

แทนรัก ทิพย์อินทร์

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image




Vehicle Front Right Image




Vehicle Rear Left Image




Vehicle Rear Right Image



Vehicle Registration Book



Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis




Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O (S2)	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status




S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2723	7
2. Front Right Tire Condition	Normal	2723	7
3. Back Left Tire Condition	Normal	3323	7
4. Back Right Tire Condition	Normal	3323	7



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12
3. Charging Voltage(V.)	15

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
12. Front right seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report


Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ GLC250**Chassis number :** WDC2533466L021060**Inspection date :** 2024-07-18

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมไม่พบหลักฐานการซ่อมแซมทำสี /บังโคลนหน้าซ้าย ถลอกฝากระปรงหน้าสีเป็นพดพื้น/ สภาพยางปกติกั้ง4เส้น ปี23 ภายใน(Interior) : ภายในปกติ สะอาดเรียบร้อย ,อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิดปกติ (ไม่ได้ทดสอบขับขี่) โครงสร้าง(Frame) : อุบัติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE