



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-23
Tel.	:	Lemon Inspection ID	: LEMON24070357
Inspector	: นายภาบุญยันน์ กัสบุก	Approved By	: ไก่รัก กิพย์อินทร์

Details

Brand	MERCEDES BENZ	Model year	2021
Model	C300	Engine Code - No.	27492031961345
Sub-model	e AMG Sport	Registration year	2021-07-13
Registration No.		Chassis No.	W1K2050536L062503
Current Mileage(km.)	93788	Engine Capacity(cc.)	1991

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

นายภาบุญยันน์ กัสบุก


Approved By

ไก่รัก กิพย์อินทร์

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image



Vehicle Rear Left Image



Vehicle Rear Right Image




Vehicle Registration Book

4
M 204100

รายการจดทะเบียน

วันจดทะเบียน	13 กุมภาพันธ์ 2564	เลขที่จดทะเบียน	ก ๔๒๖๒๑ ๔๗๖๔๗๔
ประเภท	รถยนต์น้ำมันดีเซลไม่เกิน 7 ตัน (รถ. ๑)	ลักษณะ	จักรยานยนต์
ยี่ห้อรถ	MERCEDES BENZ	แบบ	C 300 e
ล ๓	เลขตัวรถ	W1K2050536L062503	วันปี พ.ศ. 2021
ยี่ห้อเครื่องยนต์	MERCEDES BENZ	เลขเครื่องยนต์	27492031961345
อุปที่ ช่วงเครื่อง	เชื้อเพลิง	เบนซิน-ไฟฟ้าแบบสืบเนื่อง	จดทะเบียน
จ ๔	ปี 1991	ล ๒๑๑	เมล่า ๔ ล้อ ยาง ๔ เส้น
น้ำหนักบรรทุก	1800 กก.	น้ำหนักบรรทุก/น้ำหนักกล่องเพล่า	กก.
น้ำหนักรวม	1800 กก.	ที่นั่ง ๕ คน	คน
11168232			
เจ้าของรถ			
ล ๑	วันที่ครอบครองรถ	13 กุมภาพันธ์ 2564	

Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis




Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S1)	15. Left wing mirror	O (S1)
3. Front Right Fender	O (S1)	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O (S1)	18. Rear right fender	O (S2)
6. Front Left Wheel	O	19. Rear Bonnet	O (S1)
7. Front bonnet	O (S1)	20. Back Right Wheel	O
8. Right wing mirror	O (S1)	21. Rear Bumper	O (S1)
9. Front right door	O (S1)	22. Rear Skirt	O
10. Rear right door	O (S1)	23. Rear left fender	O (S1)
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left door	O (S2)	25. Back Windshield	O
13. Front left door	O (S2)		


Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing


Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade



Vehicle Defect Notices




Vehicle Defect Notices



Vehicle Defect Notices




Vehicle Defect Notices




Vehicle Defect Notices



Vehicle Defect Notices






Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	3422	5
2. Front Right Tire Condition	Normal	3422	5
3. Back Left Tire Condition	Normal	3122	5
4. Back Right Tire Condition	Normal	3122	5



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.5
3. Charging Voltage(V.)	14.8

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
12. Front right seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	


Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report


Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ C300**Chassis number :** W1K2050536L062503**Inspection date :** 2024-07-23

Inspector : ภายนอกมีรอยขีดข่วนกลอกรถกันน้ำอยรอบคัน / ยางสภาพปกติ ปี 22 ภายใน : อุปกรณ์อำนวยความสะดวก ความสะอาดภายใน ใช้งานได้ปกติ / ภายในไม่มีกลิ่นอับ / ไฟหลังคามีรอยเจ็บ เครื่องยนต์และเกียร์ : ไม่พบคราบน้ำมัน เกียร์ และคราบน้ำมันเครื่องรั่วซึม / ตรวจสอบด้วยเครื่อง OBD ไม่พบโค้ดผิดปกติ / ช่วงล่างสามารถใช้งานได้ โครงสร้าง : ไม่พบความเสียหายหนักถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE