



# Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-20
Tel.	:	Lemon Inspection ID	: LEMON24070349
Inspector	: นายภาณุวัฒน์ กัสสุภา	Approved By	: แทนรัก ทิพย์อินทร์

### Details

Brand	MERCEDES BENZ	Model year	2019
Model	GLA250	Engine Code - No.	27092031899359
Sub-model	AMG Dynamic	Registration year	2020-07-03
Registration No.		Chassis No.	WDC1569446L013527
Current Mileage(km.)	124381	Engine Capacity(cc.)	2000

### Inspection Lists

### Grading


1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector นายภาณุวัฒน์ กัสสุภา Approved By แทนรัก ทิพย์อินทร์



**Vehicle Front Image**



**Vehicle Back Image**



**Vehicle Front Left Image**




**Vehicle Front Right Image**






Vehicle Rear Left Image



Vehicle Rear Right Image



### Vehicle Registration Book



### Vehicle Engine Image





Vehicle Odometer Image




Vehicle Chassis Image



**Vehicle Engine Number Image**




**OBD Vehicle Identity Analysis**







**OBD Vehicle Health Analysis**




**Passenger Front Console Image**



**Passenger Front Seat Image**




**Passenger Ceiling Part Image**






**Passenger Back Seat Image**



### Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

## Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S1)	15. Left wing mirror	O (S1)
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front bonnet	O (S1)	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear skirt	O (S1)
10. Rear right door	O (S1)	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left door	O (S1)	25. Back Windshield	O
13. Front left door	O (S1)		


### Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

### Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

**Vehicle Defect Notices**







**Vehicle Defect Notices**



**Vehicle Defect Notices**









**Vehicle Defect Notices**



**Tire Condition Report**

Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Bald Tire	0821	2
2. Front Right Tire Condition	Swelling	0821	2
3. Back Left Tire Condition	Normal	0821	6
4. Back Right Tire Condition	Normal	0821	6




**Battery Condition Report**

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.4
3. Charging Voltage(V.)	15



Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS















Chassis Damage Level	No Damage
----------------------	-----------








### Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

**Interior Report**

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	



17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	

### Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	FAIL	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		



**Flood Report**

Evidence of Flood	No
-------------------	----



**Fire Report**

Evidence of Fire	No
------------------	----



**Inspector Note**

**Vehicle :** MERCEDES BENZ GLA250

**Chassis number :** WDC1569446L013527

**Inspection date :** 2024-07-20

**Inspector :** ภายนอก : พบรอยขีดข่วนตลอด ฝากระโปรงหน้า/กันชนหน้า/ขอบประตูหลังขวา/กันชนท้าย /ประตูหลังซ้าย/ประตูหน้าซ้าย/กระจกมองข้างฝั่งซ้าย/สภาพยาง ยางล้อหน้าซ้ายและล้อหน้าขวาเสื่อมสภาพ ยางปี 21 ภายใน : อุปกรณ์อำนวยความสะดวกภายในใช้งานได้ปกติ/ภายในมีคราบสกปรกเล็กน้อยสามารถทำความสะอาดออกได้/ภายในไม่มีกลิ่นอับ/บริเวณแป้นเบรคพวงมาลัยมีรอยถลอกเล็กน้อย เครื่องยนต์และเกียร์ : พบคราบน้ำมันเครื่องรั่วซึมบริเวณท่ออากาศหน้าเครื่อง/ไม่สามารถตรวจสอบด้วยเครื่อง OBD ได้เนื่องจากเวอร์ชันเครื่องตรวจไม่รองรับกับรุ่นนี้/ช่วงล่างใช้งานได้ปกติ โครงสร้าง : โครงสร้างในสภาพปกติไม่พบความเสียหายหนักถึงโครงสร้าง

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE