



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-07-26
Tel.	:	Lemon Inspection ID	: LEMON24070474
Inspector	: มนต์ มนต์	Approved By	: ใจมั่นคง ไพรเลี่ยง

Details

Brand	MERCEDES BENZ	Model year	2021
Model	GLA200	Engine Code - No.	28291430608931
Sub-model	AMG Dynamic	Registration year	2022-10-10
Registration No.		Chassis No.	W1N2477876L002105
Current Mileage(km.)	16404	Engine Capacity(cc.)	1300

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

มนต์ มนต์


Approved By

ใจมั่นคง ไพรเลี่ยง

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image




Vehicle Rear Right Image



Vehicle Registration Book



Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis



Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S2)	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status





S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Swelling	4920	2
2. Front Right Tire Condition	Swelling	4920	2
3. Back Left Tire Condition	Swelling	4920	3
4. Back Right Tire Condition	Swelling	4920	3



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.5
3. Charging Voltage(V.)	13.8

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
12. Front right seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report

Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ GLA200**Chassis number :** W1N2477876L002105**Inspection date :** 2024-07-26**Inspector :** ตัวถังภายนอก : พับบริเวณกันชนหน้ามีรอยขีดข่วนกลอก ยางเสื่อมสภาพกั้ง4เส้น ปี20 ภายในห้องโดยสาร : ไม่มีคราบสกปรกวิทยุเครื่องเสียงอุปกรณ์อำนวยความสะดวกใช้งานได้ปกติ เครื่องยนต์กลไก : ตรวจสอบด้วย obd2 ไม่พบโค้ดผิดปกติ โครงสร้าง : ไม่มีความเสียหายถึงโครงสร้างหลัก**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE