

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-08-02
Tel.		Lemon Inspection ID	: LEMON24080041
Inspector	: แทนรักษ์ ทิพย์อ่อนร์	Approved By	: ไซย์มงคล ไพรเลี่ยง

Details

Brand	MERCEDES BENZ	Model year	2019
Model	C300	Engine Code - No.	27492031892394
Sub-model	e Avantgarde	Registration year	2024-01-17
Registration No.		Chassis No.	WDD2050536L055707
Current Mileage(km.)	58282	Engine Capacity(cc.)	2000

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

แทนรักษ์ ทิพย์อ่อนร์

Approved By

ไซย์มงคล ไพรเลี่ยง

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Registration Book




Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis



Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S1)	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O (S1)	18. Rear right fender	BP
6. Front Left Wheel	O	19. Rear Bonnet	BP
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	BP
9. Front right door	O (S1)	22. Rear Skirt	O
10. Rear right door	O (S1)	23. Rear Left Fender	O
11. Right Skirt	O	24. Back left wheel	O (S1)
12. Rear Left door	O (S1)	25. Back Windshield	O
13. Front left door	O (S1)		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing



Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	0123	5
2. Front Right Tire Condition	Normal	0123	5
3. Back Left Tire Condition	Normal	1023	5
4. Back Right Tire Condition	Normal	1023	5



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.8
3. Charging Voltage(V.)	15

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
12. Front right seat	<div style="width: 80%; background-color: #2e8b57; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	


Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report


Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ C300 5uhn2972**Chassis number :** WDD2050536L055707**Inspection date :** 2024-08-02

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอก โดยรวมพบหลักฐานการซ่อมแซมทำสีมาบางชิ้น ฝ่ากায์ กอดทำสี รั้วรอยขีดข่วนเล็กน้อย / สภาพยางปักติดกัน 4 เส้น ปี 23 กะยใน(Interior) : ภายในเบาะเป็นรอยคลอก พ้าบุ หลังคาเป็นรอยเจมและคราบเปื้อนเล็กน้อย ,อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ
เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII พบร่องรอยดีบุ๊ค คุณย์บริการ / หน้าปัดแจ้งเตือนแบบเตอร์สำรองเสื่อมสภาพ (ไม่ได้กดสอบขับชี้) **โครงสร้าง(Frame) :** อุบติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง หมายเหตุ หน้าปัดเรื่องโนิค แจ้งเตือนแบบเตอร์สำรองเสื่อมสภาพ เช็ค ด้วยเครื่อง OBDII พบค็อด B11C1FA / P06047 / P061FF คิดกัน 3 ตัว หน้าจะเกิดจากแรงดันแบบเตอร์สำรองตัว แนะนำตัววิธีเช็คโดยละเอียดอีกครั้ง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE