



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-08-14
Tel.		Lemon Inspection ID	: LEMON24080195
Inspector	: สุวัฒน์ ทองพิมพ์	Approved By	: แทนรัก ทิพย์อินทร์

Details

Brand	MERCEDES BENZ	Model year	2021
Model	GLB200	Engine Code - No.	28291480523454
Sub-model	Progressive	Registration year	2024-04-11
License Plate		Chassis No.	W1N2476872W113569
Current Mileage(km.)	50977	Engine Capacity(cc.)	1300

Inspection Lists


Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★


This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector	สุวัฒน์ ทองพิมพ์	Approved By	แทนรัก ทิพย์อินทร์
-----------	------------------	-------------	--------------------

Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image




Vehicle Front Right Image



Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Registration Book

รายการจดทะเบียน

วันจดทะเบียน 11 เมษายน 2567 เลขทะเบียน (รย. 1) จังหวัด กรุงเทพมหานคร

ประเภท รถยนต์ส่วนบุคคลไม่เกิน 7 คน (รย. 1) ลักษณะ ขี่สามล้อ

ยี่ห้อรถ MERCEDES BENZ แบบ GLB 200 รุ่นปี ค.ศ. 2021

สี เทา เลขตัวรถ W1N2476872W113569 อยู่ที่ โต๊ะนั่งขวา

ยี่ห้อเครื่องยนต์ MERCEDES BENZ เลขเครื่องยนต์ 28291480523454

อยู่ที่ ขวาเครื่อง เชื้อเพลิง เบนซิน เลขถังแก๊ส

จำนวน 4 สูบ 1332 ซีซี 163 แรงม้า 2 เพลา 4 ล้อ ยาง 4 เส้น

น้ำหนักรถ 1600 กก. น้ำหนักบรรทุก/น้ำหนักลงเพลา กก.

น้ำหนักรวม 1600 กก. ที่นั่ง 7 คน


12629389

นาย พงษ์โชค ศรีท่าจีน


เจ้าของรถ

ลำดับที่ 1 วันที่ครอบครองรถ 11 เมษายน 2567


Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis




OBD Vehicle Health Analysis




Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	BP	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front bonnet	BP	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front right door	BP	22. Rear Skirt	O
10. Rear right door	N	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	1723	8
2. Front Right Tire Condition	Normal	1723	8
3. Back Left Tire Condition	Normal	1723	8
4. Back Right Tire Condition	Normal	1723	8



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.8
3. Charging Voltage(V.)	15

Chassis Report



Damage Level

No Damage

Level A


Level B

Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

















Chassis Damage Level	No Damage
----------------------	-----------








Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report

Evidence of Flood



No



Fire Report

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ GLB200

Chassis number : W1N2476872W113569

Inspection date : 2024-08-14

Inspector : หมายเหตุ* ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมพบหลักฐานการซ่อมแซมทำสีคือ ฝากระโปรงหน้า ประตูหน้าหลังขวา แก้มหน้าซ้าย ประตูหลังขวาเปลี่ยน/ สภาพยางปกติทั้ง4เส้น ปี23 ภายใน(Interior) : ภายในปกติไม่มีความเสียหาย สะอาดเรียบร้อย ,อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ
เครื่องยนต์(Electric) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบข้อผิดพลาดปกติ (ไม่ได้ทดสอบขับเคลื่อน) โครงสร้าง(Frame) : อุบัติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE