



# Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-09-17
Tel.	: _____	Lemon Inspection ID	: LEMON24090149
Inspector	: ແກນຮັກ ທີພຍົມອົບນົກ	Approved By	: Yoskongsak B

## Details

Brand	MERCEDES BENZ	Model year	2020
Model	E300	Engine Code - No.	27492031902429
Sub-model	e AMG Dynamic	Registration year	2021-08-02
License Plate		Chassis No.	W1K2130536L031163
Current Mileage(km.)	180866	Engine Capacity(cc.)	1991

## Inspection Lists

## Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector

ແກນຮັກ ທີພຍົມອົບນົກ


Approved By

Yoskongsak B

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




## Vehicle Rear Left Image



## Vehicle Rear Right Image



## Vehicle Registration Book



## Vehicle Engine Image



## Vehicle Odometer Image




## Vehicle Chassis Image




## Vehicle Engine Number Image




## OBD Vehicle Identity Analysis



## OBD Vehicle Health Analysis




## Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



## Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

**Exterior Inspection Report**

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S1)	15. Left Wing Mirror	O
3. Front Right Fender	O (S1)	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear right fender	O (S1)
6. Front Left Wheel	O (S1)	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front left door	O (S1)		


**Main Status**

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

**Sub Status**

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Vehicle Defect Notices





Vehicle Defect Notices



## Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2122	5
2. Front Right Tire Condition	Bald Tire	3718	4
3. Back Left Tire Condition	Normal	3622	4
4. Back Right Tire Condition	Bald Tire	2021	4



## Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	11.9
3. Charging Voltage(V.)	13.6

## Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage	PASS
No deform chassis or chassis frame	PASS
No visible corrosion on the chassis or chassis frame	PASS
No missing part on the chassis frame	PASS
Half cut Analysis	PASS

Chassis Damage Level	No Damage
----------------------	-----------

## Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

## Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
12. Front right seat	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e71b5; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	

**Vehicle Overview**

1. Vehicle Engine Number Analysis	PASS	14. Air Conditioning and Heating System	PASS
2. Vehicle Chassis Number Analysis	PASS	15. Front and Rear Suspension	PASS
3. Vehicle Original OEM Color Analysis	PASS	16. Drive Axle	PASS
4. Engine System	PASS	17. High Tech	PASS
5. Transmission System	PASS	18. Passenger Comfort	PASS
6. Electrical System	PASS	19. Security System	PASS
7. Brake System	PASS	20. Safety Active	PASS
8. Steering System	PASS	21. Safety Passive	PASS
9. Fuel System	PASS	22. Original Mileage Analysis	PASS
10. Four-wheel Drive	PASS	23. Overall Chassis Analysis	PASS
11. Turbocharger/Supercharger	PASS	24. Overall Exterior Analysis	PASS
12. Fuel Injection and Engine Management System	PASS	25. Overall Interior Analysis	PASS
13. Engine Cooling System	PASS		

**Flood Report**


Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



## Inspector Note

**Vehicle :** MERCEDES BENZ E300**Chassis number :** W1K2130536L031163**Inspection date :** 2024-09-17

**Inspector :** ภายนอก(Exterior) : พบรการกำลังไฟกระปองหน้า 1 ชั้น / รั้วรอยขีดข่วนเล็กน้อย / ยางเสื่อมสภาพ 2 เส้น  
แม็กเป็นรอยคลอก ภายใน(Interior) : เบาะหน้าขวาเป็นรอยคลอกเล็กน้อย เครื่องยนต์(Engine) : วิเคราะห์ปัญหาด้วย  
เครื่อง OBDII พบร่องผิดปกติ P26000 P008A84 P00C600 P06E900 แบบนำตรวจเช็ค (ไม่ได้ทดสอบขับขี่) /  
แบบเตอร์สำรองเสื่อมสภาพ โครงสร้าง(Frame) : -

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE