



# Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-09-17
Tel.	: <a href="tel:08123456789">08123456789</a>	Lemon Inspection ID	: LEMON24090155
Inspector	: ເອກົງລົງ ປັສີລາວ	Approved By	: Chaimongkol C

## Details

Brand	MERCEDES BENZ	Model year	2022
Model	C43	Engine Code - No.	27682331150726
Sub-model	AMG 4MATIC (Coupe)	Registration year	2023-03-15
License Plate		Chassis No.	W1K2053646L066435
Current Mileage(km.)	21155	Engine Capacity(cc.)	3000

## Inspection Lists

## Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.


Inspector

ເອກົງລົງ ປັສີລາວ


Approved By

Chainongkol C

Vehicle Front Image



Vehicle Back Image




## Vehicle Front Left Image




## Vehicle Front Right Image




Vehicle Rear Left Image




Vehicle Rear Right Image




## Vehicle Registration Book



## Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




## Vehicle Engine Number Image




## OBD Vehicle Identity Analysis



## OBD Vehicle Health Analysis




## Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



## Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

**Exterior Inspection Report**

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O (S1)
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		


**Main Status**

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

**Sub Status**




S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



## Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	4323	5
2. Front Right Tire Condition	Normal	4323	5
3. Back Left Tire Condition	Normal	5123	5
4. Back Right Tire Condition	Normal	5123	5



## Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.4
3. Charging Voltage(V.)	14.5

## Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------

## Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

## Interior Report

1. Dashboard	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
2. Sound system and monitor	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
3. Air conditioning system	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
4. Console	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
5. Steering wheel and control panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
6. Gear knob	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
7. Left Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
8. Right Headliner	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
9. Left power window master	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
10. Front left door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
11. Front left seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
12. Front right seat	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
13. Window control switch, front right door	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
14. Front right door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
15. Right rear power window master switch	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>
16. Right rear door panel	<div style="width: 100%; background-color: #2e8b57; height: 10px;"></div>

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	


**Vehicle Overview**

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

**Flood Report**

Evidence of Flood

No

**Fire Report**

Evidence of Fire

No



## Inspector Note

**Vehicle :** MERCEDES BENZ C43**Chassis number :** W1K2053646L066435**Inspection date :** 2024-09-17

**Inspector :** ภายนอก : ไม่พบหลักฐานการทำสีเก็บสี กันชนก้ายหัดข่วน สภาพยางปักติกั้ง 4 เส้น ปี 23 ภายใน : โดยรวมสะอาดเรียบร้อย อุปกรณ์ไฟฟ้าทำงานได้ปกติ เครื่องยนต์ : เครื่องยนต์สามารถทำงานได้ครบปกติ ไม่พบคราบน้ำมันรั่วซึม ตรวจสอบด้วย OBD wu code /P008A84 แรงดันในวงจรแรงดันต่ำ เชือเพลิงมากเกินไปต่ำ มีสัญญาณต่ำกว่าค่าจำกัดที่ได้รับอนุญาต /U012287 ระบบควบคุมความเร็วอัตโนมัติผิดปกติ /P1C5C00 Battery แรงดันแบบเตอร์ผิดปกติ โครงสร้างหลักปกติ ไม่พบหลักฐานการซ่อมแซม

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE