



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-09-18
Tel.	:	Lemon Inspection ID	: LEMON24090163
Inspector	: ไซมมงคล ไพโรเสียง	Approved By	: Tanrak T

Details

Brand	MERCEDES BENZ	Model year	2019
Model	C300	Engine Code - No.	27492031798482
Sub-model	e AMG Dynamic	Registration year	2019-10-09
License Plate		Chassis No.	WDD2050536L049611
Current Mileage(km.)	42510	Engine Capacity(cc.)	2000

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.


Inspector

ไซมมงคล ไพโรเสียง


Approved By

Tanrak T


Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image




Vehicle Front Right Image



Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Registration Book

รายการจดทะเบียน

วันจดทะเบียน 9 ตุลาคม 2562 เลขทะเบียน [REDACTED] จังหวัด กรุงเทพมหานคร

ประเภท รถยนต์นั่งส่วนบุคคลไม่เกิน 7 คน (รย. 1) ลักษณะ เก่งสองตอน

ยี่ห้อรถ MERCEDES BENZ แบบ C 300 e รุ่นปี ค.ศ. 2019

สี ดำ เลขตัวรถ WDD2050536L049611 อยู่ที่ ใต้ที่นั่งขวา

ยี่ห้อเครื่องยนต์ MERCEDES BENZ เลขเครื่องยนต์ 27492031798482

อยู่ที่ ซ้ายเครื่อง เชื้อเพลิง เบนซิน-1ฟฟ้า เลขถังแก๊ส

จำนวน 4 สูบ 1991 ซีซี 211 แรงม้า 2 เกลา 4 ล้อ ยาง 4 เส้น

น้ำหนักรถ 1800 กก. น้ำหนักบรรทุก/น้ำหนักลงเพล่า กก.

น้ำหนักรวม 1800 กก. ที่นั่ง 5 คน

10291101

10291101

เจ้าของรถ

ลำดับที่ 1 วันที่ครอบครองรถ 9 ตุลาคม 2562

Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis




OBD Vehicle Health Analysis




Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear right fender	O (D2)
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		


Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status





S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Swelling	4118	5
2. Front Right Tire Condition	Worn Down	4118	5
3. Back Left Tire Condition	Worn Down	3718	5
4. Back Right Tire Condition	Worn Down	3718	5



Battery Condition Report

Conditions Report	Details
1. Battery Status	Fail
2. Resting Voltage(V.)	11
3. Charging Voltage(V.)	11

Chassis Report



Damage Level

No Damage

Level A


Level B

Level C

No dent in the under carriage	PASS
No deform chassis or chassis frame	PASS
No visible corrosion on the chassis or chassis frame	PASS
No missing part on the chassis frame	PASS
Half cut Analysis	PASS

Chassis Damage Level	No Damage
----------------------	-----------

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



Vehicle Overview

1. Vehicle Engine Number Analysis	PASS	14. Air Conditioning and Heating System	PASS
2. Vehicle Chassis Number Analysis	PASS	15. Front and Rear Suspension	PASS
3. Vehicle Original OEM Color Analysis	PASS	16. Drive Axle	PASS
4. Engine System	PASS	17. High Tech	PASS
5. Transmission System	PASS	18. Passenger Comfort	PASS
6. Electrical System	PASS	19. Security System	PASS
7. Brake System	PASS	20. Safety Active	PASS
8. Steering System	PASS	21. Safety Passive	PASS
9. Fuel System	PASS	22. Original Mileage Analysis	PASS
10. Four-wheel Drive	PASS	23. Overall Chassis Analysis	PASS
11. Turbocharger/Supercharger	PASS	24. Overall Exterior Analysis	PASS
12. Fuel Injection and Engine Management System	PASS	25. Overall Interior Analysis	PASS
13. Engine Cooling System	PASS		

Flood Report

Evidence of Flood

No



Fire Report

Evidence of Fire

No



Inspector Note

Vehicle : MERCEDES BENZ C300

Chassis number : WDD2050536L049611

Inspection date : 2024-09-18

Inspector : ภายนอก(Exterior) : บังโคลนหลังขวาบุบ สภาพยางเสื่อมทั้ง4เส้น ปี18 ภายใน(Interior) : -
เครื่องยนต์(Engine) : แบบเตอरीเสื่อมสภาพ / วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิดปกติ (ไม่ได้ทดสอบขับเคลื่อน)
โครงสร้าง(Frame) : -

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE