

# Pre-owned Car Certificate

Mercedes-Benz vehicle are checked comply to  
Mercedes-Benz Thailand requirements



**VIN:** W1N2477876L012900

**Inspection Report No.:** 148

**Inspection Date:** 20/03/2025

**KM Status:** 11372

## Grading Level

**3A** = Excellent Condition (No repaint or parts damage)

**A** = Good Condition (a parts re-painted or slightly damage)

**B** = Normal Condition (several parts repainted or slightly damage)

**C** = Poor Condition (medium/heavy accident, no or poor rework)

*Pataramonadee* 27 MAR 2025

Signature / Date

On behalf of **BGAC MB Automotive Engineering**


**VIN:** W1N2477876L012900  
**Inspection Report No.:** 148  
**Inspection Date:** 20/03/2025  
**KM Status:** 11372

---

### Photo documentation - Exterior



Front Right View



Front View




Front Left Side View



Front Right Side View



Rear Left Side View




Rear View

VIN: W1N2477876L012900  
Inspection Report No.: 148  
Inspection Date: 20/03/2025  
KM Status: 11372

---

### Photo documentation - Interior



Cockpit




Media Display




Instrument Cluster



Center Console




Front Entrance




Rear Entrance

**VIN:** W1N2477876L012900  
**Inspection Report No.:** 148  
**Inspection Date:** 20/03/2025  
**KM Status:** 11372


### Photo documentation - Engine / Aggregates





Engine



Underbody




Front Left / Right Axle



Rear Left / Right Axle



Front Left / Right Wheel



Rear Left / Right Wheel

VIN: W1N2477876L012900  
Inspection Report No.: 148  
Inspection Date: 20/03/2025  
KM Status: 11372

---



## Scope of visual check based on MBTh requirements

### A. Scope of visual inspection

Visual check of accident / flooding damage / impact on body, paint surface and underbody parts:

- |                                    |                                     |
|------------------------------------|-------------------------------------|
| N = No damage                      | <input checked="" type="checkbox"/> |
| S = Minor damage                   | <input type="checkbox"/>            |
| M = Medium damage                  | <input type="checkbox"/>            |
| L = Large / heavy damage or impact | <input type="checkbox"/>            |
| X = Extra damage or impact         | <input type="checkbox"/>            |

### Damage areas



### B. Summarize condition statement

- None